

## SN36 bulb out

Submitted by MattWingo on Mon, 2013-05-13 09:55

Date:

Monday, May 13, 2013 - 09:30

### Instrument List:

- [Yellow](#)

Discussion:

One of the bulbs for SN36 has burnt out. It will be replaced either today or tomorrow.

SN38 parts will be shipped from Austria tomorrow.

SN70 required video signal adjustment. During the adjustments, it was noticed that the camera side mirror frame screws were loose. These screws were tightened improving the video signal. Sensitivity to temperature changes should now be improved as well.

---