

SN36 Down

Submitted by MattWingo on Mon, 2013-05-20 20:58

Date:

Monday, May 20, 2013 - 20:45

Instrument List:

- [Yellow](#)

Discussion:

SN36 is down due to a faulty hardware/software issue with the network temperature sensor. JR will attempt a remote fix.

The other five units are operating normally.
